



## CAS-3263 Pole Thin Box Mount

### Product Guide:



### Package Contents:

- CAS-3263
- with M8x16 screw x4
- washer-8 x4
- spring washer x4
- stainless steel straps x4

### Installation steps:

1. Fasten the Pole Thin Box Mounting on a pole with equipped stainless straps.
2. Run the cable(s) through the hole on the Pole Thin Box Mounting.
3. Fasten the CAS-3201 Mini Pendant (Optional Accessories) Mount onto the Pole Thin Box Mounting with the supplied screws and washers. Then thread the cable(s) through the CAS-3201 Mini Pendant (Optional Accessories) Mount with the cable(s) coming out of the Pendant Mount's outlet.
4. Attach the Waterproof Rubber to the CAS-3201 Mini Pendant (Optional Accessories).
5. Thread the cable(s) through the Pole Thin Box Mount and join the Pole Thin Box Mount to the CAS-3201 Mini Pendant (Optional Accessories) Mount with the supplied screws and washers. Then adjust the Waterproof Rubber to the joint.
6. Connect the cable(s) to the Dome Camera.
7. Join the Dome Camera to the Pole Thin Box Mount with the supplied screw and washers.